


• Maschi a macchina

• Machine Tap

new



M010P6H



- 1.1
- 1.2
- 1.3
- 1.4
- 1.5
- 6.1
- 6.3
- 7.1
- 7.2
- 7.3
- 7.4
- 1.6
- 3.1
- 3.2
- 3.3
- 3.4
- 4.1
- 4.2
- 5.1
- 5.2
- 6.2
- 8.1

M	P	l <sub>1</sub>	l <sub>2</sub>	d <sub>2</sub>	□	l <sub>3</sub>	z	↔	l <sub>4</sub>
	mm	mm	mm	mm	a	mm			mm
2	0.40	50	6	2.8	2.1	5	3	1.6	9
2.5	0.45	50	8	2.8	2.1	5	3	2.1	12.5
3	0.50	56	9	3.5	2.7	6	3	2.5	18
3	0.50	56	10	2.2	1.8	4	3	2.5	
3.5	0.60	56	11	4.0	3.0	6	3	2.9	20
4	0.70	63	12	4.5	3.4	6	3	3.3	21
4	0.70	63	12	2.8	2.1	5	3	3.3	
4.5	0.75	70	13	6.0	4.9	8	3	3.8	25
5	0.80	70	13	6.0	4.9	8	3	4.2	25
5	0.80	70	13	3.5	2.7	6	3	4.2	
6	1.00	80	15	6.0	4.9	8	3	5.0	30
6	1.00	80	15	4.5	3.4	6	3	5.0	
7	1.00	80	15	7.0	5.5	8	3	6.0	30
8	1.25	90	18	8.0	6.2	9	3	6.8	35
8	1.25	90	18	6.0	4.9	8	3	6.8	
10	1.50	100	20	10.0	8.0	11	3	8.5	39
10	1.50	100	20	7.0	5.5	8	3	8.5	
12	1.75	110	23	9.0	7.0	10	3	10.3	
14	2.00	110	25	11.0	9.0	12	3	12.0	
16	2.00	110	25	12.0	9.0	12	3	14.0	
18	2.50	125	30	14.0	11.0	14	4	15.5	
20	2.50	140	30	16.0	12.0	15	4	17.5	
22	2.50	140	34	18.0	14.5	17	4	19.5	
24	3.00	160	38	18.0	14.5	17	4	21.0	
27	3.00	160	38	20.0	16.0	19	4	24.0	
30	3.50	180	45	22.0	18.0	21	4	26.5	